Nucor-Yamato Proposed Roll/Cast Schedule * ISO 9001:2008 Registered * September 8, 2010

Week Beginning		5-Sep	12-Sep	19-Sep	26-Sep	3-Oct	10-Oct	17-Oct	24-Oct	
NYS Fiscal Month		Sep	Sep	Sep	Sep	Oct	Oct	Oct	Oct	
NYS Fiscal Week		36	37	38	39	40	41	42	43	
Wide Flange Sections	Prod. Mill	roll wk - cast date	roll wk - cast date	roll wk - cast date	roll wk - cast date	roll wk - cast date	Shutdown			
W44x16x230-335	2						Shutdown		43 O	
W40x16x199x431	2						Shutdown		43 O	
W40x12x149-327	2						Shutdown		43 O	
W36x16.5x231-441	2						Shutdown		43 O	
W36x12x135-256	2			>>>>	38 Cast		Shutdown			10/31 Wk 44
W33x15.75x201-387	2						Shutdown			10/31 Wk 44
W33x11.5x118-169	2				39 I 9/8		Shutdown			10/31 Wk 44
W30x15x173-391	2						Shutdown			11/7 Wk 45
W30x10.5x90-148	2				39 I 9/20	39 I 9/20	Shutdown			11/7 Wk 45
W27x14x146-368	2						Shutdown			11/7 Wk 45
W27x10x84-129	2	35 Cast			>>>>	39 I 9/20	Shutdown			11/7 Wk 45
W24x12.75x104-370	2	35 Cast				40 I 9/22	Shutdown			11/7 Wk 45
W24x9x56-103	2			38 Cast			Shutdown		43 O	11/28 Wk 48
W24x7x55-62	1				38 I 9/9		Shutdown		43 O	11/21 Wk 47
W21x12.25x101-275	2			38 Cast			Shutdown		43 O	11/28 Wk 48
W21x8.25x48-93	1				38 I 9/9		Shutdown		43 O	11/21 Wk 47
W21x6.5x44-57	1				38 I 9/9		Shutdown			10/31 Wk 44
W18x11x76-311	2			38 Cast	38 Cast		Shutdown		43 O	11/28 Wk 48
W18x7.5x41-71	1					40 I 9/21	Shutdown			11/7 Wk 45
W18x6x35-46	1					40 I 9/21	Shutdown			11/7 Wk 45
W16x10.25x67-100	1				39 I 9/22	39 I 9/22	Shutdown			10/31 Wk 44
W16x7x36-57	1					39 I 9/22	Shutdown			10/31 Wk 44
W16x5.25x26-31	1			37 Cast PS			Shutdown		43 O	11/21 Wk 47
W14x16x426-730	2		37 Cast				Shutdown			11/28 Wk 48
W14x16x145-398	2	36 Cast					Shutdown			11/21 Wk 47
W14x14.5x90-132	2				39 Cast		Shutdown			10/31 Wk 44
W14x10x61-82	1						Shutdown	42 I 9/17		11/7 Wk 45
W14x8x43-53	1						Shutdown	42 I 9/17		11/7 Wk 45
W14x6.75x30-38	1						Shutdown	42 I 9/17		11/7 Wk 45
W14x5x22-26	1			38 Cast PS			Shutdown		43 O	11/21 Wk 47
W12x12x65-336	2			38 Cast			Shutdown		43 O	11/28 Wk 48
W12x10x53-58	1					40 I 9/20	Shutdown			11/7 Wk 45
W12x8x40-50	1					40 I 9/20	Shutdown			11/7 Wk 45
W12x6.5x26-35	1		37 Cast PS	37 Cast PS			Shutdown		43 I 10/1	11/21 Wk 47
W10x10x49-112	1					39 I 9/22	Shutdown			10/31 Wk 44
W10x8x33-45	1						Shutdown	42 I 9/17		11/7 Wk 45
W10x5.75x22-30	1		37 Cast PS				Shutdown		43 I 9/30	11/14 Wk 46
W8x8x31-67	1		37 Cast PS				Shutdown	42 I 9/29		11/14 Wk 46
W8x6.5x24-28	1		37 Cast PS				Shutdown	42 9/29		11/14 Wk 46
Standard Sections		36	37	38	39	40	41	42	43	
MC18x4x42.7-58	1						Shutdown		43 O	
MC13x4x31.8x50	1						Shutdown			TBA
MC12x4x31-50	1						Shutdown	42 I 9/30		
C15x3 3/8x33.9-50	1						Shutdown	42 I 9/28		
C12x3x20.7-30	1		37 Cast				Shutdown			
L8x8x1/2" - 1 1/8"	1		37 Cast				Shutdown			11/14 Wk 46
L8x6x1/2" - 1"	1						Shutdown	42 I 9/28		
CZ13x41.2-51.2	1						Shutdown			TBA
S24x80-121	1						Shutdown		43 SA	
S20x66-96	1						Shutdown			10/31 Wk 44 SA
S18x54.7-70	1					40 I 9/21	Shutdown			
S15x42.9-50	1			37 Cast			Shutdown			
S12x31.8-50	1					40 I 9/20	Shutdown			
Piling Sections		36	37	38	39	40	41	42	43	
PS31	1									
PS27	1									
PZ40	1									
PZ35	1									
PZ27	1	37 Cast	37 Cast				Shutdown			11/14 Wk 46
PZ22	1	37 Cast	37 Cast				Shutdown			11/14 Wk 46
HP14x14.5x73-117	2	38 Cast	38 Cast	38 Cast		43 I 9/24	Shutdown	43 I 9/24	43 I 9/24	11/28 Wk 48
HP12x12x53-84	2						Shutdown			
HP12x12x53-84	1				39 I 9/13		Shutdown			10/31 Wk 44
HP10x10x42-57	1					39 I 9/22	Shutdown			10/31 Wk 44
HP8x8x36	1		37 Cast				Shutdown	42 I 9/29		11/14 Wk 46

I = Inquire O = Open Cast PS = Planned Stock SA = Subject to Accumulation E = Controlled C - Closed