

Close Dates for all items, if available, are shown immediately behind the status of the book week.
 Status: C - Closed; E - Controlled; I - Inquire; O - Open; PS - Planned Stock; SA - Subject to Accumulation

All sections close at 4 PM CST on the date indicated. Inquire items can close at any time.

Week Beginning		21-Apr	28-Apr	5-May	12-May	19-May	26-May	2-Jun	9-Jun	Projected Next Week
NYS Fiscal Week		17	18	19	20	21	22	23	24	
Wide Flange	Mill #									
W44x16x230-408	2		17 C				21 O			6/23-6/30 Wks
W40x16x199-655	2		17 C				22 O			6/23-6/30 Wks
W40x11.75x149-392	2		17 C				22 O			6/23-6/30 Wks
W36x17x487-652	2		17 C				22 O			6/23-6/30 Wks
W36x16 1/2x231-441	2		17 C	17 C			22 O	22 O		6/23-6/30 Wks
W36x12x135-387	2			17 C PS			>>>>	22 O		6/23-6/30 Wks
W33x15 3/4x201-387	2			18 C				23 O		6/30-7/7 Wks
W33x11 1/2x118-169	2			18 C PS				23 O		6/30-7/7 Wks
W30x15x173-433	2			18 C				23 O		6/30-7/7 Wks
W30x10 1/2x90-148	2			18 C PS	18 C PS			23 O		6/30-7/7 Wks
W27x14x146-539	2				19 C				24 O	7/7-7/14 Wks
W27x10x84-129	2				19 C PS				24 O	7/7-7/14 Wks
W24x12 3/4x104-370	2				19 I 4/22				24 O	7/7-7/14 Wks
W24x9x56-103	2				19 I 4/22				24 O	7/7-7/14 Wks
W24x7x55-62	1	shutdown	18 C PS			21 O	21 O			6/23-6/30 Wks
W21x12 1/4x101-275	2								24 O	7/7-7/14 Wks
W21x8 1/4x48-93	1	shutdown	18 C PS				22 O			6/23-6/30 Wks
W21x6 1/2x44-57	1	shutdown	18 C PS				22 O			6/23-6/30 Wks
W18x11x76-311	2	16 C PS	16 C PS			21 I 5/1	21 I 5/1			6/9-6/16 Wks
W18x7 1/2x41-71	1	shutdown		20 C PS			22 O			6/30-7/7 Wks
W18x6x35-46	1	shutdown		20 C PS			22 O	22 O		6/30-7/7 Wks
W16x10 1/4x67-100	1	shutdown		20 C				23 O		6/30-7/7 Wks
W16x7x36-57	1	shutdown		20 C PS				23 O		6/30-7/7 Wks
W16x5 1/2x26-31	1	shutdown				21 I 5/1				6/16-6/23 Wks
W14x16x455-808	2	14 C				20 I 4/30				6/9-6/16 Wks
W14x16x145-426	2	14 C			20 I 4/25	20 I 4/25				6/9-6/16 Wks
W14x14 1/2x90-132	2	16 C PS				21 I 5/1				6/9-6/16 Wks
W14x10x61-82	1	shutdown	20 C				22 O			6/23-6/30 Wks
W14x8x43-53	1	shutdown	20 C PS				22 O			6/23-6/30 Wks
W14x6 3/4x30-38	1	shutdown		20 C				23 O		6/30-7/7 Wks
W14x5x22-26	1	shutdown				21 I 5/1				6/16-6/23 Wks
W12x12x65-336	2		17 C PS				21 I 5/2			6/16-6/23 Wks
W12x10x53-58	1	shutdown		20 C PS				23 O		6/30-7/7 Wks
W12x8x40-50	1	shutdown		20 C PS				23 O		6/30-7/7 Wks
W12x6 1/2x26-35	1	shutdown			20 I 4/29					6/16-6/23 Wks
W12x4x16-22	1	shutdown								7/7-7/14 Wks
W10x10x49-112	1	shutdown		20 C PS	20 C PS				24 O	7/7-7/14 Wks
W10x8x33-45	1	shutdown			20 C PS				24 O	7/7-7/14 Wks
W10x5 3/4x22-30	1	shutdown			21 I 4/29					6/16-6/23 Wks
W8x8x31-67	1	shutdown			21 I 4/30					6/16-6/23 Wks
W8x6 1/2x24-28	1	shutdown			21 I 4/30					6/16-6/23 Wks
W8x5 1/4x18-21	1	shutdown			20 I 4/25				24 O	7/7-7/14 Wks
W6x6x15-25	1	shutdown			20 I 4/25				24 O	7/7-7/14 Wks
Stand Sections		21-Apr	28-Apr	5-May	12-May	19-May	26-May	2-Jun	9-Jun	
MC18x4x42.7-58	1	shutdown								6/16-6/23 Wks
MC13x4x31.8x50	1	shutdown								TBA
MC12x4x31-50	1	shutdown								6/16-6/23 Wks
C15x3 3/8x33.9-50	1	shutdown							24 O	8/4-8/11 Wks
C12x3x20.7-30	1	shutdown							24 O	8/4-8/11 Wks
L8x8x1/2" - 1 1/8"	1	shutdown				21 I 4/30				7/14-7/21 Wks
L8x6x1/2" - 1"	1	shutdown				21 I 4/30				7/14-7/21 Wks
L8x4x1/2"-1"	1	shutdown				21 I 4/30				7/14-7/21 Wks
CZ13x41.2-51.2	1	shutdown								TBA
S24x80-121	1	shutdown								6/23-6/30 Wks
S20x66-96	1	shutdown								6/23-6/30 Wks
S18x54.7-70	1	shutdown						23 O		TBA
S15x42.9-50	1	shutdown				21 I 5/1				TBA
S12x31.8-50	1	shutdown			20 I 4/29					TBA
Piling Sections		21-Apr	28-Apr	5-May	12-May					
PS31	1	shutdown								7/7-7/14 Wks
PS27	1	shutdown								7/7-7/14 Wks
PZ40	1	shutdown	18 C							7/7-7/14 Wks
PZ35	1	shutdown	18 C							7/7-7/14 Wks
PZ27	1	shutdown								7/7-7/14 Wks
PZ22	1	shutdown								7/7-7/14 Wks
HP18	2				20 I 4/25					TBA
HP16	2					20 I 4/25				TBA
HP14x14.5x73-117	2	16 C				21 I 5/2				6/9-6/16 Wks
HP12x12x53-84	2		17 C				21 I 5/2			6/16-6/23 Wks
HP10x10x42-57	1	shutdown		20 C	20 C				24 O	7/7-7/14 Wks
HP8x8x36	1	shutdown			21 I 4/30					6/16-6/23 Wks

