

Close Dates for all items, if available, are shown immediately behind the status of the book week.
 Status: C - Closed; E - Controlled; I - Inquire; O - Open; PS - Planned Stock; SA - Subject to Accum

All sections close at 4 PM CST on the date indicated. Inquire items can close at any time.

Week Beginning		19-Mar	26-Mar	2-Apr	9-Apr	16-Apr	23-Apr	30-Apr	7-May	Projected Next Week
NYS Fiscal Week	Mill #	12	13	14	15	16	17	18	19	
W44x16x230-335	2			14 3/21	shutdown					5/28-6/4 Wks
W40x16x199-655	2			14 3/21	shutdown			18 O		5/28-6/4 Wks
W40x11.75x149-392	2			14 3/21	shutdown			18 O		5/28-6/4 Wks
W36x17x487-652	2			16 3/22	shutdown			18 O		5/28-6/4 Wks
W36x16 1/2x231-441	2			16 3/22	shutdown			18 O		5/28-6/4 Wks
W36x12x135-256	2			16 3/22	shutdown			18 O		5/28-6/4 Wks
W33x15 3/4x201-387	2			16 3/23	shutdown				19 O	6/4-6/11 Wks
W33x11 1/2x118-169	2			16 3/23	shutdown				19 O	6/4-6/11 Wks
W30x15x173-433	2				shutdown	16 3/23				6/4-6/11 Wks
W30x10 1/2x90-148	2				shutdown	16 3/30			19 O	6/4-6/11 Wks
W27x14x146-368	2				shutdown	16 3/29				5/14-5/21 Wks
W27x10x84-129	2				shutdown	16 3/29				5/14-5/21 Wks
W24x12 3/4x104-370	2	12 C			shutdown	16 4/3				5/14-5/21 Wks
W24x9x56-103	2	12 C			shutdown	16 4/3				5/14-5/21 Wks
W24x7x55-62	1			14 3/23	shutdown				19 O	6/11-6/18 Wks
W21x12 1/4x101-275	2	12 C			shutdown					5/14-5/21 Wks
W21x8 1/4x48-93	1			14 3/23	shutdown	14 3/23				5/7-5/14 Wks
W21x6 1/2x44-57	1			>>>>	shutdown	14 3/23				5/7-5/14 Wks
W18x11x76-311	2		13 C		shutdown		17 O			5/28-6/4 Wks
W18x7 1/2x41-71	1				shutdown	16 4/3				5/14-5/21 Wks
W18x6x35-46	1				shutdown	16 4/3				5/14-5/21 Wks
W16x10 1/4x67-100	1	11 C			shutdown	16 3/30	16 3/30			5/14-5/21 Wks
W16x7x36-57	1	11 C			shutdown	>>>>	16 3/30			5/14-5/21 Wks
W16x5 1/2x26-31	1		13 C		shutdown			18 O		6/4-6/11 Wks
W14x16x455-730	2	13 C			shutdown					5/21-5/28 Wks
W14x16x145-426	2	13 C			shutdown		17 O			5/21-5/28 Wks
W14x14 1/2x90-132	2	13 C	13 C		shutdown		17 O			5/28-6/4 Wks
W14x10x61-82	1			>>>>	shutdown	16 3/27				5/7-5/14 Wks
W14x8x43-53	1			>>>>	shutdown	16 4/3				5/7-5/14 Wks
W14x6 3/4x30-38	1	11 C			shutdown					5/14-5/21 Wks
W14x5x22-26	1		13 C		shutdown			18 O		6/4-6/11 Wks
W12x12x65-336	2		14 C		shutdown			18 O		5/28-6/4 Wks
W12x10x53-58	1	11 C			shutdown		17 3/30			5/21-5/28 Wks
W12x8x40-50	1	11 C			shutdown		17 3/30			5/21-5/28 Wks
W12x6 1/2x26-35	1	12 C			shutdown		>>>>	17 O		5/21-5/28 Wks
W12x4x16-22	1			14 C	shutdown					6/4-6/11 Wks
W10x10x49-112	1	11 C			shutdown		17 3/29			5/21-5/28 Wks
W10x8x33-45	1	11 C			shutdown		17 3/29			5/21-5/28 Wks
W10x5 3/4x22-30	1	12 C			shutdown		>>>>	17 O		5/28-6/4 Wks
W8x8x31-67	1	12 C			shutdown		>>>>	17 O		5/28-6/4 Wks
W8x6 1/2x24-28	1	12 C			shutdown		>>>>	17 O		5/28-6/4 Wks
W8x5 1/4x18-21	1				shutdown		17 O			6/18-6/25 Wks
W6x6x15-25	1				shutdown		17 O			6/18-6/25 Wks
Stand Sections		19-Mar	26-Mar	2-Apr	9-Apr	16-Apr	23-Apr	30-Apr	7-May	
MC18x4x42.7-58	1		12 C		shutdown					5/28-6/4 Wks SA
MC13x4x31.8x50	1				shutdown					TBA
MC12x4x31-50	1	>>>>	12 C		shutdown					5/28-6/4 Wks SA
C15x3 3/8x33.9-50	1	12 C			shutdown					5/21-5/28 Wks
C12x3x20.7-30	1	12 C			shutdown					5/21-5/28 Wks
L8x8x1/2" - 1 1/8"	1				shutdown			18 O SA		TBA
L8x6x1/2" - 1"	1				shutdown			18 O SA		TBA
L8x4x1/2"-1"	1				shutdown			18 O SA		TBA
CZ13x41.2-51.2	1				shutdown					TBA
S24x80-121	1				shutdown					TBA
S20x66-96	1			>>>>	shutdown	16 3/27 SA				TBA
S18x54.7-70	1				shutdown	16 4/3 SA				TBA
S15x42.9-50	1				shutdown			18 O SA		TBA
S12x31.8-50	1				shutdown		17 O SA			TBA
Piling Sections		19-Mar	26-Mar	2-Apr	9-Apr	16-Apr	23-Apr	30-Apr	7-May	
PS31	1		>>>>	13 C	shutdown					5/28-6/4 Wks SA
PS27	1				shutdown					5/28-6/4 Wks SA
PZ40	1			13 C	shutdown					5/28-6/4 Wks SA
PZ35	1				shutdown					5/28-6/4 Wks SA
PZ27	1			14 C	shutdown					6/4-6/11 Wks SA
PZ22	1			14 C	shutdown					6/4-6/11 Wks SA
HP18	2				shutdown	16 O SA				6/11-6/18 Wks SA
HP16	2				shutdown		17 O SA			6/11-6/18 Wks SA
HP14x14.5x73-117	2		13 C		shutdown		17 O			5/28-6/4 Wks
HP12x12x53-84	2		14 C		shutdown			18 O		5/28-6/4 Wks
HP10x10x42-57	1	11 C			shutdown		17 3/29			5/21-5/28 Wks
HP8x8x36	1	12 C			shutdown		17 O			5/28-6/4 Wks