

Nucor-Yamato Proposed Roll/Close Schedule * ISO 9001:2015 Registered * September 23, 2022

Close Dates for all items, if available, are shown immediately behind the status of the book week.

Status: C - Closed; E - Controlled; I - Inquire; O - Open; PS - Planned Stock; SA - Subject to Accum

All sections close at 4 PM CT on the date indicated. Inquire items can close at any time.

Week Beginning		25-Sep	2-Oct	9-Oct	16-Oct	23-Oct	30-Oct	6-Nov	13-Nov	Projected Next Week
NYS Fiscal Week		39	40	41	42	43	44	45	46	
Wide Flange	Mill #									
W44x16x230-335	2		40 C	Shutdown				45 O		12/4-12/11 Wks
W40x16x199-655	2		42 C	Shutdown	<<<<			45 O		12/11-12/18 Wks
W40x11.75x149-392	2			Shutdown	42 C			45 O		12/11-12/18 Wks
W36x17x487-652	2			Shutdown	42 9/26				46 O	12/11-12/18 Wks
W36x16 1/2x231-441	2			Shutdown	42 9/26				46 O	12/11-12/18 Wks
W36x12x135-256	2			Shutdown	42 9/26				46 O	12/11-12/18 Wks
W33x15 3/4x201-387	2			Shutdown	42 9/27				46 O	12/11-12/18 Wks
W33x11 1/2x118-169	2			Shutdown	42 9/27				46 O	12/11-12/18 Wks
W30x15x173-433	2			Shutdown	43 9/27				46 O	12/11-12/18 Wks
W30x10 1/2x90-148	2			Shutdown	43 10/3	43 10/3				11/20-11/27 Wks
W27x14x146-368	2			Shutdown		43 10/3				11/20-11/27 Wks
W27x10x84-129	2			Shutdown		43 10/3				11/20-11/27 Wks
W24x12 3/4x104-370	2			Shutdown		43 10/4				11/20-11/27 Wks
W24x9x56-103	2			Shutdown		44 10/4				11/27-12/4 Wks
W24x7x55-62	1			Shutdown		43 10/5				11/20-11/27 Wks
W21x12 1/4x101-275	2			Shutdown						11/27-12/4 Wks
W21x8 1/4x48-93	1	39 C		Shutdown		43 10/5				11/20-11/27 Wks
W21x6 1/2x44-57	1	39 C		Shutdown		43 10/6	43 10/6			11/20-11/27 Wks
W18x11x76-311	2		40 C	Shutdown				45 O		12/18-12/25 Wks
W18x7 1/2x41-71	1	40 C		Shutdown			44 O			11/27-12/4 Wks
W18x6x35-46	1	40 C		Shutdown			44 O			11/27-12/4 Wks
W16x10 1/4x67-100	1	40 C		Shutdown			45 O	45 O		12/4-12/11 Wks
W16x7x36-57	1	40 C		Shutdown			45 O	45 O		12/4-12/11 Wks
W16x5 1/2x26-31	1			Shutdown	43 9/29				46 O	12/11-12/18 Wks
W14x16x455-730	2	39 C		Shutdown			44 O			11/27-12/4 Wks
W14x16x145-426	2	38 C		Shutdown		44 O	44 O			11/27-12/4 Wks
W14x14 1/2x90-132	2	39 C	39 C	Shutdown			45 O	<<<<		11/27-12/4 Wks
W14x10x61-82	1	40 C		Shutdown			44 10/6			11/27-12/4 Wks
W14x8x43-53	1	40 C		Shutdown			44 O			11/27-12/4 Wks
W14x6 3/4x30-38	1		40 C	Shutdown				45 O		12/4-12/11 Wks
W14x5x22-26	1			Shutdown	43 9/29				46 O	12/11-12/18 Wks
W12x12x65-336	2		40 C	Shutdown				45 O		12/18-12/25 Wks
W12x10x53-58	1		40 C	Shutdown				45 O		12/4-12/11 Wks
W12x8x40-50	1		40 C	Shutdown				45 O		12/4-12/11 Wks
W12x6 1/2x26-35	1		42 9/26	Shutdown				45 O		12/4-12/11 Wks
W12x4x16-22	1			Shutdown	43 10/5					1/1-8 Wks
W10x10x49-112	1		42 C	Shutdown				45 O		12/4-12/11 Wks
W10x8x33-45	1		42 C	Shutdown				45 O		12/4-12/11 Wks
W10x5 3/4x22-30	1		42 9/26	Shutdown	<<<<			45 O		12/4-12/11 Wks
W8x8x31-67	1		42 9/26	Shutdown	<<<<			45 O		12/4-12/11 Wks
W8x6 1/2x24-28	1			Shutdown	42 9/26				46 O	12/11-12/18 Wks
W8x5 1/4x18-21	1		42 C	Shutdown						12/25-1/1 Wks
W6x6x15-25	1		42 C	Shutdown						12/25-1/1 Wks
Stand Sections		25-Sep	2-Oct	9-Oct	16-Oct	23-Oct	30-Oct	6-Nov	13-Nov	
MC18x4x42.7-58	1			Shutdown						12/11-12/18 Wks
MC13x4x31.8x50	1			Shutdown						TBA
MC12x4x31-50	1			Shutdown						12/11-12/18 Wks
C15x3 3/8x33.9-50	1			Shutdown						12/4-12/11 Wks
C12x3x20.7-30	1			Shutdown						12/4-12/11 Wks
L8x8x1/2" - 1 1/8"	1			Shutdown						12/11-12/18 Wks
L8x6x1/2" - 1"	1			Shutdown						12/11-12/18 Wks
L8x4x1/2"-1"	1			Shutdown						12/11-12/18 Wks
CZ13x41.2-51.2	1			Shutdown						TBA
S24x80-121	1			Shutdown						TBA
S20x66-96	1			Shutdown						TBA
S18x54.7-70	1			Shutdown						11/27-12/4 Wks SA
S15x42.9-50	1			Shutdown					46 SA	TBA
S12x31.8-50	1			Shutdown						12/4-12/11 Wks SA
Piling Sections		25-Sep	2-Oct	9-Oct	16-Oct	23-Oct	30-Oct	6-Nov	13-Nov	
PS31	1		43 SA 10/3	Shutdown	<<<<					1/1-1/8 Wks SA
PS27	1			Shutdown	43 SA 10/3					1/1-1/8 Wks SA
PZ40	1			Shutdown	43 SA 10/3					1/1-1/8 Wks SA
PZ35	1			Shutdown	43 SA 10/3					1/1-1/8 Wks SA
PZ27	1			Shutdown	43 SA 10/3	43 SA 10/3				1/1-1/8 Wks SA
PZ22	1			Shutdown		43 SA 10/3				1/1-1/8 Wks SA
HP18	2			Shutdown		44 SA				TBA
HP16	2			Shutdown			44 SA			TBA
HP14x14.5x73-117	2		39 C	Shutdown				45 O		12/4-12/11 Wks
HP12x12x53-84	1	39 C		Shutdown			44 10/6			11/27-12/4 Wks
HP10x10x42-57	1		42 C	Shutdown				45 O		12/11-12/18 Wks
HP8x8x36	1		42 9/26	Shutdown				45 O		12/4-12/11 Wks